# Oil Field Environmental Incident Summary

Incident: 20151013174828 **Date/Time of Notice:** 10/13/2015 17:48 Responsible Party: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC LIBERTY RESOURCES MANAGEMENT COMPANY, LLC Well Name: JOHNSON 21-3 Field Name: GLASS BLUFF Well File #: 10878 Date Incident: 10/5/2015 Time Incident: 12:00 Facility ID Number: **MCKENZIE** County: **Twp:** 151 **Rna**: 103 **Sec**: 3 Location Description: Johnson 21-3 Well site. Submitted By: Tappan Souther Received By: Contact Person: Tappan Souther 1200 17TH STREET, SUITE 2200 DENVER, CO 80202 General Land Use: Well/Facility Site Affected Medium: Well/Facility Soil **Distance Nearest Occupied Building:** Distance Nearest Water Well: Type of Incident: Tank Overflow Release Contained in Dike: Yes - On Constructed Well Site Reported to NRC: No Spilled Units Recovered Units Followup **Units** Oil **Brine Barrels Barrels** Other Description of Other Released Contaminant: Four bbls of produced water overflowed out of the top of a storage tank. Inspected: Written Report Received: Clean Up Concluded: Risk Evaluation: None

Tuesday, January 31, 2017

All water contained in a plastic lined berm.

Areal Extent:

### Potential Environmental Impacts:

None

## Action Taken or Planned:

Discussed diligent operations with operator.

Wastes Disposal Location: Local disposal.

Agencies Involved:

## **Updates**

Date: 10/14/2015 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

Release, due to a tank overflow, remained on constructed well site according to the report. NDIC retains oversight.